

SECRET

PRIORITY

P 051431Z SEPT 69

FM NPIC WASHDC

TO RHCOAAA/SAC OFFUTT AFB OMAHA NEB

RHCOAAA/544TH ARTW OFFUTT AFB OMAHA NEB

RUCILBA/100TH SRW OL 19 MCCOY AFB FLA

RUWMDA/100TH SRW DAVIS MONTHAN AFB ARIZ

RUWMDA/12 SAD DAVIS MONTHAN AFB ARIZ

RUEBJRA/NAVRECONTECHSUPPCEN SUITLAND MD

RUEAIIA/CIA WASH DC

RUCRJCS/DIA

RUWBKNA/15TH AF MARCH AFB RIVERSIDE CALIF

RUEFHQA/HQS USAF

BT

S E C R E T CITE NPIC 6967.

SAC FOR DIRI, DOSR, DISD, DM4C, DPLC; 100 SRW DAVIS MONTHAN AFB FOR

DO, DCOI, DCM, AEMS; 12 SAD FOR MD; DIA FOR DIAXX-1; HQ USAF FOR

AFIGOS, AFXOTR; 15TH AF FOR DI, DO, DM4C.

SUBJECT: EVALUATION OF OLD HEAD MISSION G-097

1. IMAGE QUALITY: THE OVERALL IMAGE QUALITY OF THIS MISSION IS POOR DUE TO IMAGE SMEAR IN THE FLIGHT DIRECTION. THE GROUND RESOLUTION

5 SEP 69 14 44Z

OUT 68327

PAGE 2 RUEADJU 0017 S E C R E T

AND INTERPRETATION SUITABILITY ARE POOR. CLOUD COVER OBSCURES APPROXIMATELY 70 PERCENT OF THE ENTIRE MISSION.

2. MISSION DATA:

A. G-097

B. 29 AUG 69

C. B/26/U2R

D. MODE 5

E. T/O: 1045Z, C/ON: 1234Z

F. 3401

G. 1/400

H. F/11

I. MINUS BLUE (WRITTEN 12)

J. NAV RECON TECH SUPPCEN

K. LEFT SIDE: 2.05, RIGHT SIDE: 2.02

3. ORIGINAL NEGATIVE:

A. EXPOSURE: ADEQUATE WHERE NOT AFFECTED BY ATMOSPHERICS.

B. DENSITY AND CONTRAST: HEAVY DENSITY AND LOW CONTRAST IS APPARENT THROUGHOUT DUE TO THE PREDOMINANCE OF ATMOSPHERICS.

C. IMAGED DEGRADATIONS:

(1) LEFT SIDE: A 3.0 INCH BY 0.25 INCH FOG PATTERN APPEARS

PAGE 3 RUEADJU 0017 S E C R E T

ON FRAMES 5, 8, 11, 13, 15, 18, AND 21. OUTBOARD EDGE STATIC IS PRESENT THROUGHOUT THE FIRST 900 FRAMES OF THE MISSION. A WAVERING MINUS DENSITY LINE, 2 TO 3 INCHES LONG, IS PRESENT ALONG THE INBOARD EDGE INTERMITTENTLY THROUGHOUT THE FIRST 200 FRAMES.

(2) BOTH SIDES: FRAME 1 IS A MULTIPLE EXPOSURE AND IS FOGGED. MINOR INBOARD ROLLER CHATTER IS PRESENT THROUGHOUT THE MISSION. THE LAST FRAME OF THE MISSION IS SMEARED AND HEAVILY FOGGED.

D. PHYSICAL DEGRADATIONS:

(1) LEFT SIDE: A TOTAL OF FORTY INSTANCES OF HALF INCH OVERLAP OCCURS BETWEEN FRAMES 569 AND 740. A CREASE IS PRESENT IN FRAMES 260 AND 273. PROCESSING STREAKS APPEAR ON FRAMES 1249 AND 1250.

DISTRIBUTION		
CY	OFFICE	PI
5	FILE	
	CABLE SEC.	
	PP&B/RD	
	SECUR.	
3/4	TSSG/APSD	5
	PSC/OC	
	RRD	
	REFFO	
	AID	
	IEG	
	PROD	
	SCIEN	
	WEST	
	EAST	
	M&S	
	PCM	
5	IAS	
	DIA-XX4	
	SPAD	
	DIA-AP	
	25X1	
	CMX	

ADVANCE CY
SANITIZED
WITH TEXTGROUP 1
Excluded from automatic
downgrading and
declassification

— 2 —

ONE MANUFACTURER'S SPLICE AND FIVE HEAT SPLICES ARE PRESENT ON THIS MISSION.

(2) RIGHT SIDE: SLIGHT IRREGULARITY IN FILM METERING IS PRESENT THROUGHOUT THE MISSION; HOWEVER FRAME OVERLAP DOES NOT OCCUR. TWO MANUFACTURERS SPLICES AND SIX HEAT SPLICES ARE PRESENT ON THIS MISSION. ONE HEAT SPLICE IS ON THE BASE SIDE OF THE FILM.

(3) BOTH SIDES: THE RIGHT FORMAT IMAGE IS 8.75 INCHES WIDE AND THE LEFT FORMAT IMAGE IS 8.9 INCHES WIDE.

E. AUXILIARY DATA: THE COUNTER CEASED TO OPERATE AT FRAME 1000

PAGE 4 RUEADJU 0017 S E C R E T
AND STARTED AGAIN ON TITLED FRAME 1568.

F. THE LAST TITLED FRAMES ARE: LEFT SIDE 2744, RIGHT SIDE: 2744.
4. POSITIVES: PRINTING AND PROCESSING ARE ADEQUATE FOR INTERPRETATION PURPOSES.
GP-1

S E C R E T

END OF MESSAGE